

KIT GUARNIZIONI & MEMBRANE adattabili alle seguenti marche

DIAPHRAGMS & GASKET SETS to replace the following O.E.M. numbers

adattabili a (replace) **BRIGGS & STRATTON**

Art. 54.170.0900
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
291691



6B • BF • BFB • BH • BR6-F • FB • FBC • FBP • R4D • R6R • 8B-BF • BFB • BH • BHA • BRG • FBP • FBFC • P • R4D • R6 • 9B • FB • R6D • 60000 • 80000 • 140000 • 141000 • 144400 • Motori da 2-3 e 5 HP con galleggiante

Art. 54.170.0901
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
299852 - 394698




146700 • 170700 • 171700 • 190700 • 191700 • 220700 • 251700 • 394698 • serie/series 252700 • 6 hp • 7 - 8 - 10 - 11 hp vertical/vertical
Per carburatori floatanti
float type carburetors

Art. 54.170.0902
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
391071



220400 • 221400 • 243400 • 252400 • 301430 • 302430 • 325430 • Motori da 10 a 12 HP e 16 HP Albero orizzontale monocilindrici

Art. 54.170.0903
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
393397



Da (from) 253700 a (up to) 255400 • Da (from) 400400 a (up to) 422700

Art. 54.170.0904
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
394502 - 491539 - 694056



B&S 16 - 18 HP

Art. 54.170.0905
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
394693 - 291763 - 398235




14 • 14B • 14FB • 14R6 • 14R6D • 14F • 14R • 19 • 19B • 19D • 19FB • 19R6 • 19R6D • 23 • 23A • 23AB • 23B • 23C • 23D • 23R6 • 23R6D • 142300 • 143457 • 146400 • 146468 • 146700 • 146708 • 190400 • 190499 • 191400 • 191477 • 193400 • 200466 • 231401 • 231499 • 147400 • 147466 • 147700 • 147703 • 170400 • 170499 • 170700 • 170799

Art. 54.170.0906
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
394989



10, 11 & 16 HP
Motori orizzontali a cilindro singolo
Horizontal cast iron single cylinder engines

Art. 54.170.0907
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
492482



104700 • 190700 • 193700 • 251700 • Motori 5 HP OHV Vanguard 5 HP OHV Vanguard engines

Art. 54.170.0908
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
494622



92500 • 93500 • 94500 • 95500 •

Motori da 3 & 3.5 HP albero verticale

Art. 54.170.0909
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
494623



92900 • 93900 (escluso PULSA JET) • 94900 • 110900 • 111900 • 112900 • 113900 • 114900 •

Motori da 3 e 4 HP albero verticale

Art. 54.170.0911
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
494625



100900 • 130900 • 132900 •

Motori da 5 HP albero verticale

Art. 54.170.0910
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
495606



60200 • 60900 • 61200 • 61900 • 80200 • 80900 • 81200 • 81900 • 82200 • 100200 • 112200 • 130200 • 131200 • 132200 •

Art. 54.170.0912
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
PULSA JET Vecchia Serie
Early Palsa Jet



5S • 6BHS • 6BS • 6BSF • 6BSFB • 6BSR6 • 6S • 6SR6 • 60100 • 60197 • 60500 • 60597 • 61500 • 61597 • 80100 • 81097 • 81100 • 81597 • 80600 • 81600 • 84502 • 85502 •

Art. 54.170.0913
Kit riparazione completo adattabile a
Repair Kit replaces
Briggs & Stratton
PULSA JET Nuova Serie
Later Palsa Jet




60200 • 62097 • 61200 • 61297 • 60900 • 60907 • 61900 • 61907 • 80200 • 80297 • 81200 • 81292 • 80800 • 81800 • 80900 • 81900 • 84902 • 85902 • 100202 • 100293 • 130202 • 130293 • 140200 • 141200 • 144200 • 145200

**Per ulteriori modelli di
KIT GUARNIZIONI & MEMBRANE
vedere la sezione 1 del presente catalogo.**

*For additional
Diaphragm & Gasket Kit models
please see Section 1
of this catalogue*

adattabili a (replace) **BRIGGS & STRATTON**

Art. 54.170.0920
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 270026
 Confez. 10 pz - *In lots of 10*



60000 • 80000 • 91200 • 100000 • 130000
 Da 3 a 5 hp orizzontali Pulsa Jet Carb.
 (Fits 3 through 5 horiz. Pulsa-Jet Carb.)

Art. 54.170.0921
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 270253
 Confez. 10 pz - *In lots of 10*




82000 • 92000 •

Art. 54.170.0922
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 270989
 Confez. 10 pz - *In lots of 10*



Da (from) 253700 (up-to) 255400 •
 Da (from) 400400 a (up-to) 422700

Art. 54.170.0923
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 272538
 Confez. 10 pz - *In lots of 10*



3,5 hp orizzontali (horizontal)
 modelli (models)
 90200 • 90299 • 91200 • 91299 •
 5 hp orizzontali (horizontal)
 modelli (models)
 133200 • 133299 • 135200 • 135299 •

Art. 54.170.0924
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 272638
 Confez. 10 pz - *In lots of 10*



Fits selected
 8 & 11 hp horiz.
 14 16 & 18 HP L-Head Twin Engines

Art. 54.170.0925
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 299637
 Confez. 10 pz - *In lots of 10*




Carb. VacuJet - 3 hp
 albero verticale
 3 HP Vert. (Vacu-Jet Carb.)

Art. 54.170.0926
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 391681
 Confez. 10 pz - *In lots of 10*



Carb. PulsaJet 3,5 e 4 hp albero verticale
 3.5 & 4 HP Vert. (Pulsa-Jet Carb.)

Art. 54.170.0927
 Membrana adattabile a
Diaphragm replaces
Briggs & Stratton 495770
 Confez. 10 pz - *In lots of 10*



3,75 hp Sprint II - Modello 98902
 & 3.5 HP modello 95902
 3.75 HP Sprint II - Model 98902
 & 3.5 HP Model 95902

adattabili a (replace) **TECUMSEH**

Art. 54.170.0930
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 29155 - 29157 - 30359 - 31390



H22-70 •
 HH40-70 •
 V40-55 •
 VH80 •
 VH100 •
 L • LV •
 LAV •
 V • VT

Art. 54.170.0931
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631584 - 631539



H25-70 •
 LAV25-35 •
 HS •
 HM40-70 •
 V •
 VH50-70

Art. 54.170.0932
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631782



H25-70 •
 LAV25-35 •
 HS •
 HM40-70 •
 V •
 VH50-70

Art. 54.170.0933
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631893



H • LAV
 V • H • VH
 22-35
 HS40
 638
 650
 670

Art. 54.170.0934
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631173 - 631180



ECH90 •
 EVC100 •
 EVC120 •
 422-80 •
 HH40 •
 HH70 •
 HM80 •
 HS40 • LAV25 •
 HS50 • LAV50 •
 TVS70 •
 TVS120 •
 TVXL105 • 380 •
 660 • 670 • V •
 VH40 • VH70

Art. 54.170.0935
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631840



H25 • H70 •
 LAV25 • 30 •
 HS •
 HM40 •
 HM70 • V •
 VH40 •
 VH70 •
 TVS105

Art. 54.170.0936
 Kit riparazione completo adattabile a
Repair Kit replaces
Tecumseh 631029 - 631240



H25 • H50 •
 LAV25 • 35 •
 HS • HM40 •
 HM 70 •
 VH50 •
 VH 70

**Per ulteriori modelli di
 KIT GUARNIZIONI &
 MEMBRANE
 vedere la sezione 1 del
 presente catalogo.**

*For additional
 Diaphragm & Gasket Kit
 models
 please see Section 1
 of this catalogue*

SPILLI CARBURATORE adattabili alle seguenti marche

INLET NEEDLES to replace the following O.E.M. numbers

adattabili a (replace) BRIGGS & STRATTON



Art. 54.170.0940
Kit spillo adattabile a
Needle kit replaces
Briggs & Stratton
293478



3 HP - 5 HP
ORIZZONTALE
HORIZONTAL

Confez. 10 pz
In lots of 10



Art. 54.170.0941
Kit spillo adattabile a
Needle kit replaces
Briggs & Stratton
394681 - 299096

7 HP - 18 HP
ORIZZONTALE +
VERTICALE
HORIZONTAL +
VERTICAL

Confez. 10 pz
In lots of 10

Art. 54.170.0942
Kit spillo adattabile a
Needle kit replaces
Briggs & Stratton
398188

Confez. 10 pz
In lots of 10



3,5 HP - 4 HP MAX
Serie QUANTUM
5 HP VERTICALI

3,5 HP - 4 HP MAX
Quantum series
5 HP Vertical



Art. 54.170.0943
Kit spillo adattabile a
Needle kit replaces
Briggs & Stratton
293962 - 297102

6 HP - 8 HP
140000 • 170000 •
190000

Confez. 10 pz
In lots of 10

adattabili a (replace) HONDA

Art. 54.290.0706
Kit spillo adattabile a
Needle kit replaces
HONDA
16155-883-005

G150 •
G200 • G300 • GV100 • GV150



Confez. 10 pz
In lots of 10

Art. 54.290.0707

Vaschetta carburatore adattabile a
Carburetor Bowl replaces
HONDA
16015-ZE0-831

GXV140K1 • GXV160K1
GX110 • GX120 • GV140 • GX160
• GX200



adattabili a (replace) TECUMSEH

Art. 54.170.0944
Kit spillo adattabile a
Needle kit replaces
Tecumseh
630932 A
1624.0001

LAV • V • VH •
H22 • H35 • H40
H638 • 640 •
650 • 670

Confez. 10 pz
In lots of 10

Art. 54.170.0945
Kit spillo adattabile a
Needle kit replaces
Tecumseh
631021

LAV • V • VM • TNT • TVS •
H22-80 • HH40-70 •
HM80-100 • HS • 638 • 650 • 670



Confez. 10 pz
In lots of 10

adattabili a (replace) TILLOTSON

Art. 54.290.0702
Valvola a spillo adattabile a
Needle kit replaces
Tillotson
HL Vecchio Tipo (Old Type)
Tutto in alluminio

Confez. 10 pz
In lots of 10

Art. 54.290.0703
Valvola a spillo adattabile a
Needle kit replaces
Tillotson
HL Nuovo Tipo (New Type)

Confez. 10 pz
In lots of 10

Art. 54.170.0850
Kit spillo adattabile a
Needle kit replaces
Tillotson 1106 120 0607
HL 342 A

Confez. 10 pz
In lots of 10

adattabili a (replace) WALBRO

Art. 54.290.0701
Valvola a spillo adattabile a
Needle kit replaces
Walbro 82-82
Tillotson 34-210 / 34-219





Confez. 10 pz
In lots of 10

Art. 54.290.0700
Valvola a spillo adattabile a
Needle kit replaces
Walbro 82-75
Tillotson 34-216
Zama



Confez. 10 pz
In lots of 10



Art. 54.170.0851
Kit spillo adattabile a
Needle kit replaces
Tillotson 1108 120 0607
HL 166 A

Confez. 10 pz
In lots of 10



Art. 54.170.0852
Kit spillo adattabile a
Needle kit replaces
Tillotson 1111 120 0801
HS

Confez. 10 pz
In lots of 10